

SafeStat Online

August 04, 2009 SafeStat Release
Contains data as of July 24, 2009
Updated Monthly



[Overview](#) [Accident](#) [Driver](#) [Vehicle](#) [Safety](#) [History](#)

US DOT #: 824116 MC #: 366041 Carrier Name: LEX EXPRESS INC Carrier Operation: INTERSTATE Other FMCSA Websites:

Vehicle SEA Report

[How do I correct my data?](#) [Print Ready Version](#) [Help](#)

Click on the underlined text below for an explanation of how an indicator or measure was calculated.

Vehicle SEA Value: 97.68

[View Methodology](#)

Compliance Review Results
(within 18 months)

Vehicle Inspections Results
(within 30 months)

Measures and Indicators

Vehicle Review Indicator (<u>VR</u> I)	0.0	Vehicle Inspection Indicator (<u>VI</u> I)	97.7
Vehicle Review Measure (<u>VR</u> M)	0	Vehicle Inspection Measure (<u>VI</u> M)	2.052

Summary Event Data

Date of Review	05/22/2009	Number of Vehicle Inspections	20
Number of Critical Violations	0	Number of OOS Inspections	12
Number of Acute Violations	0	Vehicle OOS Rate (<u>VOR</u>)	0.6

[View Detail Data](#)

New Reports!

OOS Insps. w/ OOS Viols.

*Click on the underlined column headings to resort data records.
To view the OOS violation description click on the underlined number in the Vehicle OOS Violations column.*

NEW Click on a record # for a Detailed Inspection Report		Vehicle OOS Inspections with Vehicle OOS Violations (within 30 months)								Download Data
<u>Inspection Date</u>	<u>Report State</u>	<u>Report Number</u>	<u>Insp. Level</u>	<u>Unit Description</u>	<u>VIN Number</u>	<u>Unit License Number</u>	<u>Unit License State</u>	<u>Vehicle OOS Violations</u>		
1	5/19/2009	IL	4488001815	5	BUS	S13940	9711PT	IL	4	
Vehicle OOS Violation:		393.201(A) FRAME CRACKED / LOOSE / SAGGING / BROKEN 393.207(A) Axle positioning parts defective/missing 393.48(A) Inoperative/defective brakes 396.3A1BOS BRAKES OUT OF SERVICE: THE NUMBER OF DEFECTIVE BRAKES IS EQUAL TO OR GREATER THA								
2	5/18/2009	IL	3263001963	5	BUS	S13860	1003PT	IL	4	
Vehicle OOS Violation:		393.209(D) Steering system components worn/welded/missng 393.47(D) INSUFFICIENT BRAKE LININGS 393.47(D) INSUFFICIENT BRAKE LININGS 396.3A1BOS BRAKES OUT OF SERVICE: THE NUMBER OF DEFECTIVE BRAKES IS EQUAL TO OR GREATER THA								
3	5/18/2009	IL	3263001961	5	BUS	1M8PDMPA4SP047083	P540934	IL	3	
Vehicle OOS Violation:		393.75(C) Tire-other tread depth less than 2/32 of inch 396.3(A)(1) Inspection/repair and maint parts & accssries 396.3A1BOS BRAKES OUT OF SERVICE: THE NUMBER OF DEFECTIVE BRAKES IS EQUAL TO OR GREATER THA								
4	5/18/2009	IL	3263001962	5	BUS	1M86DM7A1LP043574	10961P	IL	3	
Vehicle OOS Violation:		393.201(A) FRAME CRACKED / LOOSE / SAGGING / BROKEN 393.75(C) Tire-other tread depth less than 2/32 of inch 396.3(A)(1) Inspection/repair and maint parts & accssries								
5	6/22/2008	MN	00KN001732	2	BUS	1M8RCM7A6RP045986	9729PT	IL	3	
Vehicle OOS Violation:		393.62(C) NO OR DEFECTIVE BUS EMERGENCY EXIT WINDOWS 396.3(A)(1) Inspection/repair and maint parts & accssries 396.7 Unsafe operations forbidden								
6	5/19/2009	IL	4488001813	5	BUS	1M8RCM7A4RP046036	10980PT	IL	2	
Vehicle OOS Violation:		396.3A1BOS BRAKES OUT OF SERVICE: THE NUMBER OF DEFECTIVE BRAKES IS EQUAL TO OR GREATER THA								
7	5/19/2009	IL	3263001965	5	BUS	1M8RCM7A6RP045986	9729PT	IL	2	
Vehicle OOS Violation:		393.48(A) Inoperative/defective brakes 393.62(C) NO OR DEFECTIVE BUS EMERGENCY EXIT WINDOWS								
8	5/19/2009	IL	4488001814	5	BUS	1M8RCM7A7SP047655	10952PJ	IL	2	
Vehicle OOS Violation:		393.9(A) INOPERABLE REQUIRED LAMP								
9	5/18/2009	IL	3600000720	5	BUS	1M8RCM7A2SP047630	10395PT	IL	2	
Vehicle OOS Violation:		393.45 Brake tubing and hose adequacy 396.3(A)(1) Inspection/repair and maint parts & accssries								
10	5/18/2009	IL	3600000721	5	BUS	1M8RCM7A7SP047610	11002PT	IL	2	
Vehicle OOS Violation:		393.45 Brake tubing and hose adequacy 393.75(C) Tire-other tread depth less than 2/32 of inch								
11	5/19/2009	IL	3263001966	5	MOTOR COACH	1M8PDM PAXTP048093	P540933	IL	1	
Vehicle OOS Violation:		393.207(A) Axle positioning parts defective/missing								
12	5/18/2009	IL	3600000722	5	BUS	1M8RCM7A9SP047656	10979PT	IL	1	

Vehicle OOS Violation: 393.45 Brake tubing and hose adequacy

12 records found. Showing page 1 of 1. Page 1

CAUTION: Please verify [important data](#) before relying on SafeStat results. Inaccurate or out-of-date normalizing data can result in SafeStat results that do not accurately reflect the motor carrier's safety status.

 [U.S. Department of Transportation](#)

[Federal Motor Carrier Safety Administration](#)



- [A&I Home](#) | [What's New](#) | [Contacts](#) | [Site Guide](#) | [A&I Data](#) | [Feedback](#)
- [Privacy Policy](#) | [Accessibility](#) | [A&I User Login](#)

